



KARNATAKA FIRE AND EMERGENCY SERVICES DEPARTMENT

Office of the District Fire Officer,
Banasawadi Fire Station, Bengaluru-560 043.
080-22971540/22971611.



No.41/SCHOOL/CC/DFO/BWFS/2025.

Date: 13-08-2025

ANNEXURE – B

Group- B Educational Building.

To,

The Chairman,
Christ International School,
Behind Garden City College,
Near Halehalli, K.R.Puram,
Bengaluru-560 036.

Sub: Issue of 'Fire Safety Compliance Report' with respect to fire prevention, fire fighting and evacuation measures maintained at *Christ International School*, Behind Garden City College, Near Halehalli, K.R.Puram, Bengaluru-560 036.

Ref: 1. FSR report No.40/SCHOOL/FSR/DFO/BWFS/2025, Dated: 13-08-2025.
2. Your request letter, Dated: 13-08-2025.
3. DFO Banaswadi inspection report, Dated: 13-08-2025.

* * * * *

With reference to subject above cited, 'fire safety recommendation' was issued wide reference (1) to the premises of *Christ International School*, comprising of ground & 02 upper floors had height 10.00 mtrs. situated at Behind Garden City College, Near Halehalli, K.R.Puram, Bengaluru-560 036 with a condition to fulfill the recommendations and compliance the same within 03 months. With reference cited (2) above, the management of *Christ International School* had requested for the fire safety compliance report from our department. In this regard with reference cited (3) above the building was inspected by me on 13-08-2025 and submitted the report & recommended to issue of fire safety compliance report.

Under the above circumstances the Karnataka Fire & Emergency Services Department is issue the "Fire Safety Compliance Report" to *Christ International School*, comprising of ground & 02 upper floors had height 10.00 mtrs. situated at Behind Garden City College, Near Halehalli, K.R.Puram, Bengaluru-560 036. Subject to proper maintenance of fire fighting systems in good working conditions and to impart training for at-least 40% of employees/staff should be trained in basic fire fighting at R.A. Mundkur Fire & Emergency Academy, Bannerghatta Road, Bengaluru at an earliest.

..1



This Fire Safety Compliance Report is issued from the Fire Prevention and Fire Fighting point of view Karnataka State Fire & Emergency Services Department is not responsible for the ownership of the land, its location and other disputes, which may arise in due course.

"In case the fire prevention and fire fighting measures installed in the building as per the recommendation of the department are not maintained in good working condition, if the evacuation measures are not properly followed and if any additional construction work is taken up in the building/premises, this Fire Safety Compliance Report deemed to be cancelled and necessary legal action will be initiated against the developer/ management/ tenant and also separate NOC has to be obtained from the department for the storage of Chemicals, Solvents, Petroleum products (Diesel/Petrol), LPG, etc in the premises/ building."

"This fire safety compliance report is issued for the period of only one year from the date of issue and it is renewable without fail".

Yours faithfully,


13/8/2025
District Fire Officer
Karnataka State Fire and Emergency Services
Banasawadi Fire Station
Banasawadi, Bengaluru - 560043.